

Securities and Exchange Commission of Pakistan State Life building 4th Floor Wallace Road-Karachi (Support Services Division)

(Administration Department)
Tel: 92-21-99213423-4, Fax: 92-21-99211379,
Email: sajjad.ahmed@secp.gov.pk

November 27, 2013

Subject: REPAIR OF TWO UPS (APC - 8KVA)

The Commission requires quotations from the financially sound firms being Dealers/Suppliers/distributors of APC brand in Pakistan and registered with income or sales tax departments, for providing and replacing invertor board of one 8KVA UPS and PFC board and batteries (12V, 5A, complete set) for another 8KVA UPS (Model APC Smart UPS-SURT8000XLI), as per terms and condition mentioned in the Annex: "A".

Terms & Conditions

- **Price** must be inclusive of all taxes applicable by Govt. of Pakistan.
- **Delivery** time within 10 days of receiving of P.O.
- **Validity** Minimum 30 Days from quoted date.
- **Bid Submission** Time within 06 days after receiving this RFQ.
- **Warranty Period:** Standard (If applicable)

Note: In case of any query you may visit the sight/location or contact undersigned.

Sealed quotations clearly marked "Quotations for repair of UPSs" may reach the above mentioned address by 2nd December, 2013.

An early and quick response will be appreciated.

With best regards.

Sajjad Ahmed Deputy Director

Terms & Conditions

- The vendor shall provide quotation for replacing invertor board of one 8KVA UPS and PFC board and batteries (12V, 5A, complete set) for another 8KVA UPS (Model APC Smart UPS- SURT8000XLI) including labor (installation) with material, complete in respect.
- Replacing of invertor board, PFC board and batteries should be done within 10days of issuance of work order.
- Vendor shall be responsible for any technical fault that may arise after replacement of invertor board, PFC board and batteries.
- Vendor shall be liable to mention the warranty period of invertor board, PFC board and batteries along with the quotation.
- The Commission reserves the right to accept or reject any or all quotations; without assigning any reason.
- Vendor has to provide genuine invertor board, PFC board and batteries, fully compatible with the model (APC Smart UPS- SURT8000XLI)
- Vendor shall be liable to reinstallation and commission of UPS at our Karachi office after repair.
- Quoted rates should be inclusive of all applicable taxes.
- "Quotations for repair of UPSs" should be clearly mentioned at the top left of the envelope.
- Quotations received by Fax or e-mail shall not be accepted. Unsealed quotations will not be attended.
- The vendor should be registered with income or sales tax departments.