



SECURITIES & EXCHANGE COMMISSION OF PAKISTAN

Subject: Quotations Required For Replacement of faulty Smoke Detectors & Filter Cartridge for Vesda.

The Commission intends to hire services of contractors /Company operated service centers for replacement faulty Smoke Detectors & Filter Cartridge for Vesda. Specifications as below:

S.No.	Item Description / Scope of Work	Qty.	Unit	Unit Price	Total Price
1	Replacement of Faulty Smoke Detectors Low Profile Design 24 V DC with two LED indicators EN54,LPCB &VdS CERTIFICATIONS C/W Base KZ 700 KILSEN,UTC Fire &Security, Spain	12			
2	Filter Cartridge for VESDA system 516..018.504	01			

TERMS & CONDITIONS

- **Price** must be inclusive of all taxes applicable by Govt. of Pakistan
- Replacement of faulty Smoke Detectors & Filter Cartridge for Vesda will be completed in two days after receipt of PO
- **Quote Validity** Minimum 30 Days from quoted date.
- **Bid Submission.** Within 04 days after receipt and posting of RFQ on website.
- **Warranty Period:** warranty of parts & repair should be mentioned.
- **Quotation** from authorized service dealers are preferred
- **NTN & GST:** numbers should be mentioned on the quote.

Note: In case of any query or visit the site Please contact undersigned

Umer Haider

Administration Department

SECURITIES & EXCHANGE

COMMISSION OF PAKIATAN

Company Registration Office; 3rd floor,

Associated House; 7-Edgerton Road, Lahore, Pakistan

Support Services Division | Administration Department

PABX: +92 [42] 99204962-66 [53] | FAX: +92 [42] 99202044