



Securities and Exchange Commission of Pakistan
State Life building # 2, 4th Floor Wallace Road-Karachi
Support Service Division/Administration Department
Tel: 92-21-99213423-4, Fax: 92-21-99211379,
Email: sajjad.ahmed@secp.gov.pk

September 6 '2013

Subject: REPAIR OF FOUR UPS (APC - 8KVA & 3KVA)

The Commission requires quotations from the financially sound firms/Dealers/Suppliers registered with income or sales tax departments, for providing and replacing of following items as per terms and condition mentioned in the Annex: "A":-

1. PFC board and Inverter board of 8KVA UPS (Model APC Smart UPS-SURT8000XLI)
2. Batteries 12v 17ah of 3KVA UPS 3 Nos (Model APC Smart UPS SUA 30001)

Terms & Conditions

- **Price** must be inclusive of all taxes applicable by Govt. of Pakistan.
- **Delivery** time within two week of receiving of P.O.
- **Validity** Minimum 30 Days from quoted date.
- **Bid Submission** Time within 11 days after receiving this RFQ.
- **Warranty Period:** Standard (If applicable)

Note: In case of any query you may visit the sight/location or contact undersigned.

Sealed quotations clearly marked "**Quotations for repair of UPS**" may reach the above mentioned address by September 16th 2013.

An early and quick response will be appreciated.

With best regards.

Sajjad Ahmed
Deputy Director

Terms & Conditions

- The vendor shall provide quotation of providing and repair of PFC board, Inverter board and Batteries 12v 17ah including labor (installation) with material, complete in respect.
- Providing and Replacing of PFC board, Inverter board and Batteries 12v 17ah should be done within 10days of issuance of work order.
- Vendor shall be responsible for any technical fault that may arise after providing and replacement of PFC board, Inverter board and Batteries 12v 17ah.
- Vendor shall be liable to mention the warranty period of providing and replacing of PFC board, Inverter board and Batteries 12v 17ah along with the quotation.
- The Commission reserves the right to accept or reject any or all quotations; without assigning any reason.
- Vendor has to provide genuine part of PFC board, Inverter board and Batteries 12v 17ah, fully compatible with the model (APC Smart UPS- SURT8000XLI and APC Smart UPS SUA 30001)
- Vendor shall be liable to reinstallation and commission of UPS at our Karachi office after repair.
- Quoted rates should be inclusive of all applicable taxes.
- **“Quotations for repair of UPS”** should be clearly mentioned at the top left of the envelope.
- Quotations received by Fax or e-mail shall not be accepted. Unsealed quotations will not be attended.
- The vendor should be registered with income or sales tax departments.