



SECURITIES & EXCHANGE COMMISSION OF PAKISTAN

Subject: Quotations Required for Replacement of Faulty Compressor

The Commission intends to hire services of contractors /Company operated service centers /authorized dealer of acson for replacement of faulty compressor of air conditioner. Specification necessary details and scope of work is as under:

SR NO	SPECIFICATION/SCOPE OF WORK	DETAIL
1	Compressor Replacement	01 Unit
2	Company Name	ACSON
3	Model No	AFS50B
4	Capacity	4 TON
5	Installation Type	STANDING UNIT

TERMS & CONDITIONS

- **Price** must be inclusive of all taxes applicable by Govt. of Pakistan
- Repair of the air conditioner will be completed in a week time after receipt of PO
- **Quote Validity** Minimum 30 Days from quoted date.
- **Bid Submission.** Within 03 days after receipt and posting of RFQ on website.
- **Warranty Period:** Standard 5 years compressor warranty should be extended in the name of SECP
- **Quotation** from authorized service dealers are preferred
- **NTN & GST:** numbers should be mentioned on the quote.

Note: In case of any query or visit the site please contact undersigned

Umer Haider

Administration Department

SECURITIES & EXCHANGE

COMMISSION OF PAKIATAN

Company Registration Office; 3rd floor,

Associated House; 7-Edgerton Road, Lahore, Pakistan

Support Services Division | Administration Department

PABX: +92 [42] 99204962-66 [53] | FAX: +92 [42] 99202044