

Subject Repair of 05 KVA UPS System.

The Commission requires quotations from firms registered with income or sales tax departments for "Repair of 05 KVA UPS System" installed SECP's Head Office, Islamabad with following specifications:

S. No.	Specifications	QTY
01	UPS make and model: APC, SRT5000VA	
02	Power Rating: 05 KVA	1
03	Problem/Fault: Repair/Replacement of Mother Board	
04	Replacement of Batteries 12V 5 AH	16

- Price: must be inclusive of all taxes applicable by Govt. of Pakistan. \triangleright
- AAAA GST/NTN numbers must be mentioned on the quotation.
- Validity: Minimum 30 days from quoted date.
- **Delivery:** time within two days of receiving of P.O.
- Warranty Period: One year.
- \triangleright In case UPS is out of work due to failure of the part provided by the vendor during the warranty period, it will be a responsibility of the vendor to replace/repair it in order to get the UPS in working condition.

Note: Interested firm/vendor may inspect/check subject item to quote accordingly.

If you are interested, please submit sealed quotation for the above item/services to the undersigned at

SECP, 63-NIC Building, Jinnah Avenue, Blue Area, Islamabad

With best regards,

Asim Ayaz M E (Admin)